




Hypothetic salt rock layer undergoing dissolution by under saturated ground water

Confirmation of the existence of a salt rock layer containing huge voids, by drillings





Exposure of the salt rock layer to dissolution by ground water following the sink of the interface, as a consequence of the drop in the level of the Dead Sea